


Spareparts ECO.50


1	020.0056	Frame
2	020.0106	Screw SSM6x16
3	020.0111	Washer M6
4	020.0096	Setting Nut
5	020.0091	Setting Screw
	020.0098	Setting set (6x No. 4+5)
6	050.0611	Magnet Hi/Lo
7	020.0201	Sensor
8	050.0011	Slide
9	032.0016	Rack
10	020.0156	Screw SSM6x20
11	050.0141	Motorholder
12	020.0146	Screw SSM6x25
13	040.0041	Top fixing plate 110mm
14	020.0086	Brass rail set (stick)
15	020.0084/4	Pressing strip 4 holes
	020.0084/6	Pressing strip 6 holes
16	020.0061	Capstan hub assembly
	020.0330	Power Assist small
17	020.0077	End plate
18	020.0081	End screw
19	020.0066	Arm for Capstan
20	020.0046	Motorcable
21	020.0041	Coupling nut for motorcable
22	020.0031	Coupling nut for maincable
23	020.0036	Main Cable
24	020.0182	Screw+washer+nut
25	PP.RSEU	Rear plate
26	020.0101	Panel screw M4x8
27	PP.50EU	Front plate
28	020.0206	Sensor LED+cable
29	020.0006	On/Off switch
30	020.0016	Fuse holder
31	020.0017	Fuse F2A
32	020.0011	Magnet switch
33	020.0001	Control Unit 220v
	020.0002	Control Unit 110v
34	020.0037	Cable clamp
35	050.0101	Motorunit 220v
	050.0102	Motorunit 110v
36	050.0586	Cable housing
37	050.0587	Screw PKVZ4,8x35
51	032.0156	Screw 3,9x60
52	050.0182	Adaptor ring 22x0,2
53	050.0161	Needle bearing
54	032.0221	Bearing 8x22x7
55	032.0171	Bearing 12x28x8
56	050.0251	First gear
57	050.0231	Axle
58	050.0246	Gear shaft
59	050.0191	Spindle drive shaft
60	050.0371	Carbon brush holder
61	050.0147	Carbon brush set
62	050.0112	Screw 4,8x45

63	032.0106	Screw 4,8x50
64	050.0116	Adaptor ring rubber 22x2,5
65	050.0466	Bearing 20x37x9
66	050.0221	Bearing 17x40x12
67	050.0177	Spindle gear
68	050.0171	Gear 34/40
69	050.0261	Baffle
70	050.0181	Armature 220v
	050.0186	Armature 110v
71	050.0276	Field 220v
	050.0277	Field 110v
72	050.0111	End cover
73	050.0142	Housing
74	050.0176	Circlip 471/10
75	050.0426	Circlip 471/15
76	050.0166	Circlip 472/28
77	050.0236	Inner gear plate
78	050.0206	Gear casing
79	050.0431	Key for spindle
80	050.0301	Key
81	032.0211	Casing pin
82	050.0291	Clutch shaft
83	040.0286	Gear switch
84	050.0211	Plate for gear casing

ECO 50



ECO 50



ELECTRICAL WIRING DIAGRAM

